

Figure 1





Figure 2






Figure 4




Figure 5




Figure 6




**Insulator  
600**

**Residual  
Hardmask  
200**


**700**

**Distinction Between Insulator  
/ 600 and Hardmask 200**

**No Erosion  
or Corner  
Rounding**



**Figure 7**

**Figure 8**